

# Technical Service Bulletin

Mazda North American Operations  
Irvine, CA 92618-2922



<b>Subject:</b>  FRONT DOOR INTERFERES WITH REAR DOOR GARNISH	<b>Bulletin No.:</b> 09-051/24
	<b>Last Issued :</b> 11/21/2024

## BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:
09-027/23	06/28/2023

## APPLICABLE MODEL(S)/VINS

2020-2023 CX-30 (Mexico built) vehicles with VINs lower than 3MV DM\*\*\*\* \*\* 528452 (Produced before Jan. 23, 2023)

## DESCRIPTION

On some vehicles, the front door glass run channel may interfere with the rear door garnish. Since the front door glass run channel is not fixed strongly enough to the door, repetition of door operation may result in interference and damage to the rear door rubber seal.



To eliminate this concern, the fixing force and durability of the glass run channel against thermal expansion and vibration has been improved. The shapes of the front and rear glass run channels and the rear garnish lip have been changed to prevent interference.

Customers experiencing this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

1. Verify the customer concern.
2. Replace the front and rear door glass run channels and rear garnish with modified parts according to the instructions on MGSS online: (FRONT DOOR GLASS RUN-CHANNEL REMOVAL/INSTALLATION), (REAR DOOR GLASS RUN-CHANNEL REMOVAL/INSTALLATION)

Page 1 of 3

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

**NOTE:**

- Replace the opposite side too, even if there is no damage.
- For this repair, the beltline molding does not need to be removed/replaced, even though the workshop manual instructs to do so.

3. Verify the repair.

**PARTS INFORMATION**

Parts Number	Description	Qty.	Notes
DGH9-58-60ZC	CHANNEL(R), GLASS	1	For front door
DGH9-59-60ZC	CHANNEL(L), GLASS	1	For front door
DGH9-72-60ZC	RUN CHANNEL(R) GLASS	1	For rear door
DGH9-73-60ZC	RUN CHANNEL(L) GLASS	1	For rear door
DGH9-50-M10	GARNISH(R), FRONT DOOR	1	[R] BLACK
DGJ1-50-M10A	GARNISH(R), FRONT DOOR	1	[R] PIANO BLACK
DGH9-50-M20	GARNISH(L), FRONT DOOR	1	[R] BLACK
DGJ1-50-M20A	GARNISH(L), FRONT DOOR	1	[R] PIANO BLACK
DGH9-50-M30A	GARNISH(R), REAR DOOR	1	BLACK
DGJ1-50-M30B	GARNISH(R), REAR DOOR	1	PIANO BLACK
DGH9-50-M40A	GARNISH(L), REAR DOOR	1	BLACK
DGJ1-50-M40B	GARNISH(L), REAR DOOR	1	PIANO BLACK
DGH9-50-M50	GARNISH(R), REAR DOOR	1	[R] BLACK
DGJ1-50-M50A	GARNISH(R), REAR DOOR	1	[R] PIANO BLACK
DGH9-50-M60	GARNISH(L), REAR DOOR	1	[R] BLACK
DGJ1-50-M60A	GARNISH(L), REAR DOOR	1	[R] PIANO BLACK
BCJH-58-975B	GROMMET, SCREW	6	[R] for hole cover No.1
BDDT-50-M38	CLIP, GARNISH	6	[R] for PIANO BLACK sail garnish (both sides)
GHP9-50-M38	CLIP, GARNISH	6	[R] for BLACK sail garnish (both sides)
-	Accessory side window deflectors	1	If already installed to the vehicle before repair

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

[R]: Replacement parts

## WARRANTY INFORMATION

### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	90
Damage Code	9B
Part Number Main Cause	DGH9-58-60ZC or DGH9-59-60ZC
Quantity	1
Operation Number / Labor Hours:	XXRC8XRX / 2.8 Hrs.

**NOTE:** Claim other parts as Related Parts.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.