

QUARANTINE N949 - SV PAINT BLOOM

| QUARANTINE N949 - SV PAINT BLOOM | |
|----------------------------------|--|
| AFFECTED MODELS | 25MY Range Rover Sport SV EDITION TWO variants only |
| VOLUME AFFECTED | US 103 CAN 14 |
| REPAIR | A potential concern has been identified on specific Range Rover Sport SV EDITION TWO vehicles where they have undergone significant uplift activity. The intensive uplift in paint polishing on a small batch of VINs has resulted in a 'blooming' effect in the paintwork. |
| REPAIR TIME | Pending repair instructions. A future communication will be sent once the official service bulletin is available. |
| CAMPAIGN LAUNCH | Quarantine Notification released on October 31st, 2024 |
| NOTES | Retailers are requested to carefully review the bulletin and hold any affected vehicles once at their store. Many affected vehicles are currently being held at Ports of Entry. No vehicle can be sold or delivered to customers until the can fix be applied. Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory. |