

## UPS N949 - SV PAINT BLOOM

UPS N949 - SV PAINT BLOOM	
AFFECTED MODELS	25MY Range Rover Sport SV EDITION 2 variants only
VOLUME AFFECTED	US 98 CAN 3
REPAIR	A concern has been identified on specific Range Rover Sport SV EDITION-2 vehicles which have undergone significant incremental paint finish related activity in the manufacturing process. The intensive paint polishing on a batch of vehicles has resulted in a 'blooming' effect in the paintwork which now requires an additional final polishing operation.
REPAIR TIME	The additional polishing process will reimburse a flat rate of approx \$300 US per VIN
CAMPAIGN LAUNCH	Quarantine Notification released on October 31st, 2024 Repair Bulletin published Nov 14 <sup>th</sup> , 2024
NOTES	Retailers are requested to hold all affected vehicles and to perform the additional paint polish process either at an approved body shop or an equivalent vehicle detailing specialist.  No vehicle can be sold or delivered to clients until this repair is completed. Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory. As of Nov 14 <sup>th</sup> 2024, there are 33 US and 3 Canadian affected vehicles are in retailer inventory