

## ENGINE COOLANT EXPANSION TANK - LEAKING BLEED SCREW

### Customer Voice:

- Smell of coolant from vehicle

### Technical Description:

- Small engine coolant leak can be found coming from the engine coolant expansion tank bleed screw.

### Status:

- After performing a engine coolant pressure test, engine coolant can be seen leaking from the bleed screw follow the steps below.

1. Remove the bleed screw.
2. Lubricate the o-ring with engine coolant.
3. Install the bleed screw and tighten to 3Nm

Refer to SSM 76209

### Range Rover

- 25MY Range Rover
- 25MY Range Rover Sport

