


UPDATE: SCRAMBLER 400 X & SPEED 400 KEY PAIRING

The release of **TDT 2024-13** includes a temporary fix to allow replacement keys to be paired to Speed 400 and Scrambler 400 X. This issue was outlined in TOL #29513 The temporary key pairing process is in the attached PDF.

 Triumph Update 400 Key Pairing.pdf

Triumph will continue to work on a full resolution for this concern which will be released in a later version of the TDT.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.