



**Bulletin No.:** PIT6274

**Published date:** 11/4/2024

## Preliminary Information

### PIT6274 Error Message Referring To Vison Camera System With DTC B1C48

#### Proactive

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet Blazer EV	2025		All All All	All	
Chevrolet Equinox EV	2025		All All All	All	

<b>Involved Region or Country</b>	<b>United States, Canada, Mexico and Europe</b>
<b>Additional Options (RPO)</b>	<b>UCV</b>
<b>Condition</b>	<b>Some customers may comment seeing a popup stating Vision/Camera system.</b>
<b>Cause</b>	<b>This is due to a software anomaly.</b>

#### Correction:

**Do not replace any parts at this time.**

**Engineering is aware of the concern.**

**The PI will be updated when a repair is available.**

**Until a fix is available, the concern can not be corrected by clearing codes.**


#### Warranty Information

**For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.**

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>
<b>3486348</b>	<b>Verify Current DTC B1C48 And Unable To Clear</b>	<b>0.2 Hr.</b>
<b>*This is a unique Labor Operation for Bulletin use only.</b>		

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>11/04/2024 - Created on.</b>

 GM Global Brands  
© 2024 General Motors. All Rights Reserved.