



Bulletin No.: PIT6271A
Published date: 11/19/2024

Preliminary Information

PIT6271A Trailer Lighting Inoperative After Accessory Hitch Installed

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox	2025	All All	All	All
GMC	Terrain	2025	All All	All	All

Involved Region or Country:	North America
Condition:	After accessory trailer hitch installation, the trailer lighting is inoperative.
Cause:	The installation instructions are being updated to include the need for the calibration. The instruction sheets will contain the authorization codes.

The accessory trailer hitch kits are currently on stop sale, pending the instruction updates.

This PI will be replaced by a bulletin when the instruction sheets are available.

Version History

Version	2.0
Modified	10/29/2024 - Created on. 11/19/2024 - Updated Models.