



**Bulletin No.:** PIT6286

**Published date:** 11/25/2024

## Preliminary Information

### PIT6286 Passengers Side Outside Mirror Reflection

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet	Silverado EV Models	2024	All	All	All
GMC	Sierra Denali EV	2024	All	All	All
Cadillac	Escalade IQ	2025	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional RPO(s)</b>	<b>DX6 Power Adjust, Heat, Power Fold, Turn Signal, Light Sensor Driver</b>
<b>Condition</b>	<b>A customer/driver could notice that the reflection/view of the passenger side outside mirror is different than the reflection/view of the drivers side outside mirror.</b>
<b>Cause</b>	<b>MVSS 111 requires that the passenger side mirror glass be flat (not convex) when the vehicle exceeds 10,000 # GVW.</b>



#### Correction:


**This is a normal characteristic of the vehicle and no repairs should be attempted.**

**Dealer technicians should educate the customer on the FMVSS requirement.**

**Any passenger side mirror replacements due to this customer concern will be charged back to the dealer.**

## Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>11/25/2024 - Created on.</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.