



Bulletin No.: PIT6249
Published date: 10/3/2024

Preliminary Information

PIT6249 Front Bumper License Plate Mounting Hole Spacing Too Wide

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 3500 HG/4500 HG Low Cab Forward	2025	All	All	All
Chevrolet	Silverado 4500 HD/4500 XD Low Cab Forward	2025	All	All	All
Chevrolet	Silverado 5500 HG/5500 XG Low Cab Forward	2025	All	All	All
Chevrolet	Silverado 5500 XD Low Cab Forward	2025	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the front bumper license plate tag mounting holes are too wide for the license plate to fit.
Cause	The cause of this condition is an error during the mounting hole stamping process.

Correction:

Do not replace the front bumper for this condition. Engineering is aware of the issue and working on releasing a mounting bracket kit. When the kit is available this PI will be updated.

Version History

Version	1
Modified	10/03/2024 - Created on.