



Bulletin No.: PIP6012
Published date: 10/8/2024

Preliminary Information

PIP6012 Service Transmission Message

Models

Brand: Chevrolet **Model:** Corvette E-Ray **Model Years:** 2024 **VIN:** All **Engine:** All LT2 **Transmissions:** MLH

Involved Region or Country	North America
Condition	Service transmission message
Cause	Dealers may find a P2797 current or in history

Correction:

If the vehicle has a p2797 that is stored current/active perform published diagnostics.

Drive the vehicle in Stealth and shuttle modes to see if concern can be reproduced with ICE off. If concern occurs with ICE off (which will force an ICE start) continue with published diagnostics.

If the vehicle has a p2797 in history and cannot be reproduced ask the customer if they noticed the service transmission message came on while the ICE was running and provide that information when creating a tac case.

Version History

Version	1
Modified	10/08/2024 Created on