



Bulletin No.: PIT6256

Published date: 10/8/2024

Preliminary Information

PIT6256 Rear Blower And Or Rear HVAC Inoperative, No DTCs

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All All	All	All
Chevrolet	Traverse (all new)	2024	All All	All	All
GMC	Acadia	2024	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	
Condition	The rear blower and or HVAC may be inoperative with no dtcs,
Cause	The rear temperature and or mode actuator connectors may not be fully seated or have poor terminal fit.

Correction:

Inspect the rear temperature and mode actuator connectors for proper terminal fit and that the connector is seated fully in the actuator.

Reseat the connector to the actuator or repair the terminals as needed.

If the connectors are properly seated, Please follow service information to root cause the condition.

Version History

Version	1
Modified	10/08/2024 - Created on.