



Bulletin No.: PIC6576

Published date: N/A

Preliminary Information

PIC6576 Diagnostic Tip for Installing Cargo Floor Mat

Models

Brand: Model: Model Years: VIN: Engine: Transmissions:
from to
 Buick Envista 2024 - 2025 All All All All


Involved Region or Country	North America
Condition	Technician may comment on their difficulties installing the GM accessory Cargo Floor Mat.
Cause	Location of seat back retaining holes for cargo mat.

Correction:

Before attempting to install the new cargo floor mat, the technician should remove the mat from its packaging and lay on a flat surface 24 hours before use.

Place the cargo mat in the rear storage compartment, aligning the rear edge of the mat against the liftgate sill plate and the right and left-hand sides with the quarter panel trim (see photos below).





Note: The cargo mat will cover the edge of the left-hand side storage bin, this is a normal condition and no modification to the mat should be made.


When aligning the cargo mat to the back of the rear seat backs, being with locating the upper outer hole (see photo below). Use of a scratch awl can help locate the holes.



To confirm that you have located the correct hole in the seat back frame, you can look thru the latch opening (see photo below).




If the holes in the seat back frame are not able to be located. The tech can remove the rear seat back cushion carpet to locate the correct holes (see photo below).



Version History

Version	1
Modified	10/08/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.