



Bulletin No.: PIT6068B

Published date: N/A

Preliminary Information

PIT6068B Service Driver Assist B1A05

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
			from to		
Cadillac	LYRIQ	2024 - 2025	All	All All	All
Chevrolet	Blazer EV	2024 - 2025	All	All All	All

Involved Region or Country	North America
Condition	Service driver assist message. On inspection B1A05 will be found in the B174W Front View Camera Module (FVCM).
Cause	Software

Correction:

Reprogram B174W FVCM using SPS.

Version History

Version	3
Modified	10/03/2023 - Created on. 10/04/2023 - Removed statement to learn FVC after programming. 10/14/2024- Updated models.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.