



Bulletin No.: PIT6242A

Published date: 10/17/2024

Preliminary Information

PIT6242A Check Engine Light Is On And U164E Is Set

Proactive

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All All	All
Chevrolet	Traverse (All New)	2024	All	All All	All
GMC	Acadia	2024	All	All All	All

Involved Region or Country	North America, Canada, Mexico
Additional Options (RPO)	IVE
Condition	Some technicians may comment that the check engine light is on and there will be a U164E setting in the radio after programming.
Cause	The radio boot settings are incorrect after programming.

Correction:

Cycle the A11 Radio fuse after programming is completed.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486258	Cycle Radio Fuse After Programming	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	09/25/2024 - Created on. 10/17/2024 - Updated Concern.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.