



Bulletin No.: PIC6582

Published date: 10/24/2024

Preliminary Information

PIC6582 Service Drivers Assist Message, Super Cruise Inoperable, U1624 Setting

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
Cadillac CT4	2025		from to	All All All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL - LANE ACTIVE SAFETY-KEEP ASSIST, HANDS FREE LANE FOLLOWING(ENTIRE SPEED RANGE)
Condition	A customer may comment of a Service Drivers Assist message and Super Cruise being inoperable. Upon inspection a U1624 may be found setting current.
Cause	Software

Correction:

Engineering is aware of this concern and is working on a resolution. Do not replace any parts.

This PI will be converted to a bulletin once a resolution is available.

Warranty Information

Version History

Version	1
Modified	10/24/2024 - Created on.