



**Bulletin No.:** PIT6267

**Published date:** 10/28/2024

## Preliminary Information

### PIT6267 History DTC U0422 Set In The K5 Automatic Air Leveling Control Module Should Be Ignored

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet Suburban		2025	All All	All	All
Chevrolet Tahoe		2025	All All	All	All
GMC Yukon Models		2025	All All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	F47
<b>Condition</b>	It maybe found that when checking the vehicle for DTCs a History U0422 is set in the K5 Automatic Level Control Module.
<b>Cause</b>	Software anomaly.

#### Correction:

If the K5 Automatic Air Level Control Module has a history DTC U0422 it should be cleared and ignored.

**NOTE:** This does not cause any customer complaints, warning messages or warning indicators.


#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8086058*	Ignore and Clear History DTC U0422 From The K5 Automatic Level Control Module	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

<b>Version</b>	1
<b>Modified</b>	10/28/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.