

# Technical product information

<b>Topic</b>	Gear selection not possible after replacing the transmission or hydraulic control unit
<b>Market area</b>	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2075769/1
<b>Level</b>	EH
<b>Status</b>	Approval
<b>Release date</b>	

## New customer code

Object of complaint	Complaint type	Position
power transmission -> operation, shift and power flow control	functionality	
power transmission -> gearbox control operation	functionality	
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	
power transmission -> gearbox control operation	component / consumables	
power transmission -> gearbox control operation -> clutch actuation	functionality -> uneven	

# Vehicle data

## Continental GT / C and Flying Spur

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S3*	2021	E		*	*	*
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S3*	2024	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*
ZG2*	2020	E		*	*	*
ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*

# Documents

Document name
<a href="#">master.xml</a>

-----

Gear selection not possible after replacing the transmission or hydraulic control unit

## Customer statement / workshop findings

After the ODIS adaption process has been conducted (post transmission or hydraulic control unit replacement)

Gear selection not possible

## Technical background

### CAUTION

In the event the transmission or hydraulic control unit has been replaced the operative must also replace the transmission control unit this issue relates to the bin file being corrupted during the adaption process

## Production change

The instructions within the Measure section must be conducted until further notice, the issue is currently under investigation

## Measure



**VERY IMPORTANT:** Once permission has been given to replace the transmission or mechatronic unit via an open DISS query the operative must be aware of the following:

- The transmission control unit **MUST** be replaced during the replacement of the transmission or hydraulic control unit
- Once replaced, the standard transmission replace test / adaption routines **MUST** be followed as per all required Elsa pro instruction

## Parts information

Refer to the ETKA parts catalogue