



**Bulletin No.:** PIT5962B

**Published date:** 12/6/2024

## Preliminary Information

### PIT5962B Reflective High Temperature Heat Or Insulating Tape For Wiring Harness Repairs

#### Models

**Brand:** All    **Model:** All Models    **Model Years:** 2010 - 2025    **VIN:** All    **Engine:** All All    **Transmissions:** All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	When performing certain repairs, such as a wiring harness repair, there maybe a reflective high temperature heat or insulating tape that may need to be replaced. In some cases, the part number for this type of tape can be difficult to locate, which is the reason for this PI.
<b>Cause</b>	Difficulty locating the part number for a reflective high temperature heat or insulating tape.

#### Correction:


If a reflective high temperature heat or insulating tape is needed then use GM part number 10184916.

#### Parts Information

Description	Part Number	QTY
Insulating Tape	10184916	2"x20' roll

#### Version History

<b>Version</b>	3
<b>Modified</b>	12/13/2022 - Created on. 12/15/2023 - Update to the models. 12/06/2024 update the model years.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.