



Bulletin No.: PIT6296

Published date: 12/9/2024

Preliminary Information

PIT6296 Brake System Control Module setting U164E as current

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2025	All	All	All	All
GMC	HUMMER SUV EV	2025	All	All	All	All

Involved Region or Country	North America
Condition	Technicians may see the Brake System Control Module reporting a U164E as current.
Cause	A software anomaly is causing U164E to set in the Brake System Control Module.

Correction:

- U164E set as current only in the EBCM does not cause any issues and can be ignored at this time, future software updates will be released to correct this issue.**
- Follow normal SI diagnostics if U164E is set current in any other modules other than the EBCM.**

Version History

Version	1
Modified	12/09/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.