

GENERAL MOTORS  
DCS7108  
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 17, 2024

Subject: REVISION: N242450160-01 – Service Update  
High Pressure Fuel Pump  
Revised Parts Table

Models: 2023-2024 Chevrolet Equinox  
2023 GMC Terrain

This bulletin is being revised to update the Parts table. Please discard all previous copies of N242450160.

END OF MESSAGE

# Service Update

## N242450160 High Pressure Fuel Pump



**Release Date:** December 2024

**Revision:** 01

**Revision Description:** This bulletin is being revised to update the Parts table. Please discard all previous copies of N242450160.

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's Emission Limited Warranty period.

Make	Model	Model Year	
		From	To
Chevrolet	Equinox	2023	2024
GMC	Terrain	2023	2023

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	Certain vehicles listed above, may have a condition where the high pressure fuel pump is potentially inoperative.
<b>Correction</b>	Dealers are to replace the high pressure fuel pump and fuel pump feed pipe.

### Parts

Quantity	Part Name	Part No.
1	High Pressure Fuel Pump	25207068
1	High Pressure Fuel Pump Feed Pipe	12708907
2	High Pressure Fuel Pump Bolts	11588724
1	Intake Manifold Gasket	12637018

**Reminder:** Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect. **Due to the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9107629	High Pressure Fuel Pump Replacement	1.5	ZFAT	N/A
9107630	Customer Reimbursement Approved - For USA and Canada dealers only - For Export dealers only	N/A 0.2	ZFAT	*
9107631	Customer Reimbursement Denied – For USA dealers only	N/A	ZFAT	**

Note: To avoid having to "H" route the customer reimbursement transaction for wholesale approval, it must be submitted prior to the repair transaction.

\*For USA & Canada: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. Submit \$20.00 USD (\$25.00 CAD) administrative allowance in Net/Admin Allowance.

For Export: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement.

\*\*Submit \$10.00 administrative allowance in Net/Admin Allowance.

### Service Procedure

**Important:** Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Replace the high pressure fuel pump. Refer to *Fuel Pump Replacement* in SI.

# Service Update

## N242450160 High Pressure Fuel Pump



### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the Emission Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

### Dealer Reports – For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

### Customer Reimbursement

Customer requests for reimbursement of previously paid repairs to correct the condition described in this bulletin are to be submitted to the dealer prior to or by November 30, 2025. See General Motors Service Policies and Procedures Manual (USA & Canada) or local Policies and Procedures, for details.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support  
Voluntary Technician  
Certification**