



Service Bulletin

Bulletin No.: PIE0802A

Date: November, 2024

ENGINEERING INFORMATION

Subject: Engineering Information - Check Engine Lamp Illuminated on the Driver Information Center (DIC), DTC P0202 Set

This PI has been revised to end the need for gathering information from the field. Please discard PIE0802.

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission :
		from	to	from	to		
Cadillac	Escalade Models	2024	2024	Vehicles Built from June 2024		Equipped with 3.0L (RPO LM2)	-
Chevrolet	Silverado 1500					Equipped with 3.0L (RPO LM2 or LZ0)	
	Suburban					Equipped with 3.0L (RPO LM2)	
	Tahoe					Equipped with 3.0L (RPO LM2 or LZ0)	
GMC	Sierra 1500					Equipped with 3.0L (RPO LM2)	
	Yukon Models	Equipped with 3.0L (RPO LM2)					

If you encounter a vehicle with the above condition, the technician will need to replace the wire harness and effected fuel injector following SI.

Version	2
Modified	Released September 23, 2024 Revised November 18, 2024 - Ended the need for gathering further information from the field.

