



**Bulletin No.:** PIT6295

**Published date:** 12/17/2024

## Preliminary Information

### PIT6295 HUD Inoperative

#### Models

**Brand:** GMC    **Model:** Canyon 2023 - 2024    **VIN:** All    **Engine:** All    **Transmissions:** All

<b>Involved Region or Country</b>	United States, Canada, Mexico and Middle East
<b>Additional Options (RPO)</b>	IVD
<b>Condition</b>	Some customers may comment the Head Up Display is inoperative.
<b>Cause</b>	The cause is unknown at this time.

#### Correction:

Engineering is investigating at this time.

Do not replace any parts.

Please communicate to the customer that GM is aware of this issue and will provide an update through a service bulletin when a fix becomes available.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
* 3486378	Verify HUD inoperative	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

<b>Version</b>	1
<b>Modified</b>	Created On 12/17/2024