

PASSIVE START INOPERATIVE- KEY LEFT IN UNLOCKED VEHICLE

Range Rover

- 22-24MY Range Rover
- 23-24MY RR Sport

JLR

Concern

Customer may report the following:

- *“Key does not respond to start vehicle when left in car”*
- *“Key buttons must be pressed to allow vehicle start”*

Technical description

Outdated RFA Software level **F188 L8B2-14C104-AV**



- Concern may occur when the vehicle is shut off and key fob is left in the vehicle for an extended period longer than 20 minutes.
- Key will not respond requiring a lock or unlock button press to allow the vehicle to recognize key and allow passive start function.

Action

Reference SSM76196

- Perform RFA module software update to **F188 L8B2-14C104-AX** or higher.

Once RFA software update is complete, function test vehicle to verify fault condition is now resolved and key remains operational.