



Bulletin No.: PIT6219A


Published date: N/A

Preliminary Information

PIT6219A Underhood Insulator and Beauty Covers/Sight Shields and Charge Cords Missing

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	LYRIQ	2025	All	All All	All
Chevrolet	Blazer EV	2025	All	All All	All
Chevrolet	Equinox EV	2025	All	All All	All

Involved Region or Country	North America
Condition	<p>It will be found that the underhood insulator and beauty covers/sight shields are missing during PDI on the 2025 model year vehicles listed above. LYRIQ is still equipped with an underhood insulator but the sight shields are no longer provided. Photo below is from a 2024 Blazer EV showing the beauty covers/sight shields installed.</p>  <p>It may also be found that the portable dual level charger assembly with interchangeable 120/240V plugs is no longer included in the vehicle.</p>
Cause	Build change.


Correction:

Do not order or install the underhood insulator or beauty covers/sight shields. Insulators and beauty covers/sight shields were deleted for model year 2025. The portable dual level charge cord is no longer standard. If the customer ordered RPO PSC the cord will be included in the PDI dealer pack.

Warranty Information

Version History

Version	2
Modified	08/20/2024 - Created on. 01/06/2025- Updated Models and Title.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.