

GPOP - Issue Review System

Part Number: 68534592A\$, 68534593A\$, 68534594A\$

Part Description: TUBE Fuel Filler

Issue Description: When there is fuel leakage at the joint of the Inlet Check Valve or the joint of the Fuel Filler Tube, place a mark on the Fuel Filler Tube of the insertion depth of the Filler Hose before removing the Hose. Check the Fuel Filler Hose for delamination or potential hole(s) or damage. Check the Inlet Check Valve (ICV) for any damage. If there is no damage found on the ICV and the Fuel Filler Hose is found to have delamination or damage, replace the Fuel Filler Hose and Clamps only. Do not replace the Fuel Filler Tube and/or the Fuel Tank. Install the new Fuel Filler Hose on the Tube to the marked location.