



## **SSM 53322 2025 Maverick/Bronco Sport - FDRS Can Not Communicate With HS2-CAN Or HS3-CAN Network**

Some 2025 Maverick and Bronco Sport vehicles may exhibit a condition where the Ford Diagnosis and Repair System (FDRS) scan tool can not communicate with the modules on the high-speed controller area network 2 (HS-CAN2) or HS-CAN3. Ford is aware of the concern and this condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Engineering is currently working on a fix for the FDRS scan tool that is expected by the end of January 2025. Replacement/reprogramming of modules will not resolve this condition. Monitor Professional Technician System (PTS) for additional information.