

Volvo Proprietary Steerable Axle Hubcap Replacement

Service Category Service Department

Section 771

Technician Skill Level C

Market US, Canada

Applicability

VOLVO

Years	Models
2021 - 2023	VAH, VHD, VN, VNE

Introduction

This Service Campaign is the solution for the **Proprietary Hubcap Recall SC0425** that effected **Volvo VAH, VHD, VN, VNE** Models. This Service Campaign also covers trucks that were shipped short from the factory or removed in the field. Volvo Trucks now has a solution to replace the Proprietary Hubcaps with new updated hubcaps.

Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Brand	Engine	Emission Level	Starting Build Date	Ending Build Date
Volvo	CU15, D11, D13, UE	USA17-24, ZE	08- September-2020	14-January-2022

Warranty Information

This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.		B
Main Labor Code	Description	Hours
7718-03-02-01	Hub Cap Wheel Cover, Replacement Per wheel	0.1
Causal Part	23768767 / 23768768	
SCC Authorization Code	S7631	
Expiration Date	December 31, 2025	

Volvo Proprietary Steerable Axle Hubcap Replacement

Parts Information

*Verify parts and quantity needed in IMPACT per VIN

Note* Hub caps are sold as a pair of two.

Part Numbers	Part Names	Quantity
24154261	HUB CAP, KIT, STEER, VOLVO, BLACK	*
24154263	HUB CAP, KIT, STEER, VOLVO, CHROME	*

Required Tools & Equipment

- N/A

Calibration Information

- N/A

Repair Procedure

1. Secure truck for service.
2. Install all new proprietary hubcap wheel covers.
3. Ensure new hubcaps are fully seated on the wheel.
4. Release the truck to service.

Volvo Proprietary Hubcap wheel cover shown below

