



SSM 53343 2025 Mustang - Passive Key Will Not Program

Some 2025 Mustang Vehicles may exhibit a condition where the passive key will not program to the vehicle. If a key does not program, try one of the following:

- * Remove the center console mat and rotate the key 180 degrees so that the unlock button points toward the rear of the vehicle in the passive key backup starting location versus what is recommended in the Owner's Manual Section > "Starting and Stopping the Engine - Accessing the Passive Key Backup Position" and then reattempt programing.
- * Remove the center console mat, place the key in front of the backup location and rotate the key 180 degrees so that the unlock button points towards the rear of the vehicle in the passive key backup starting location versus what is recommended in the Owners Manual Section > "Starting and Stopping the Engine - Accessing the Passive Key Backup Position" and then reattempt programing.
- * Place the passive key in center of the center console with the mat installed and reattempt programing.

If the key still does not program, refer to Workshop Manual (WSM), Section 419-01 for normal diagnostics.