



Bulletin No.: PIT6345
Published date: 02/21/2025

Preliminary Information

PIT6345 P059F and P05AE DTCs set in snowy or icing conditions

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox	2025	All	All	All
GMC	Terrain	2025	All	All	All

Involved Region or Country:	North America
Condition:	Vehicle may present with a CEL and DTCs P059F and P05AE.
Cause:	This is likely caused by a software anomaly mixed with snow or freezing temperatures.

Correction:


If no issue is found after completing the diagnostics in SI for both DTCs, do not replace the shutter assembly.

Engineering is currently investigating.

The PI will be updated or replaced with TSB once a determination has been made.

Version History

Version	1
Modified	02/21/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.