

Bulletin #: C32-0225-0610		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: February 27, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC729 RIGHT TIE ROD RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

32 10 6 792 030

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing wrong assembled tie rod. Parts containing correct assembled build shown below is ok for use.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC729 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC729 is valid from February 27, 2025, through March 13, 2025. The deadline for filing a claim under TEC729 is March 13, 2025. All parts must be returned to your facing RDC no later than March 27, 2025.

Please reorder same part number as needed.

