

**On-car analysis list from February 19th, 2025
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-25	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory (leak must be from fuel cap area) (Untouched vehicles)
E-Mobility	ID.4	21-24	All	All	CMCe Faults	Customer states Electrical System Error Message, U04A1 [42304], U04A5 [42336], and/or U04A9 [42444] stored in DA:008C (No other relevant DTCs stored in DA:008C)
	ID.4	23-24	All	All	No Start (Tow In)	Customer states vehicle does not start; key not detected. No communication to J519 active. AW 19: U014000[2170894][2240526], B1248F3[1074443], U17B900[8398624] active DTC's (Untouched vehicles)
Body	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress (Untouched vehicles)
	Atlas, Cross Sport	24-25	All	All	Seat Rattle	Customer states middle row seat rattles (Untouched vehicles)
Chassis	Atlas / Atlas Cross Sport	24	All	All	Driveshaft Vibration	Customer states vibration from front of the vehicle at highway speeds (Untouched vehicles)
	Atlas / Atlas Cross Sport	24	All	All	Anti-Roll Bar Coupling Link Noise	Customer states there is a noise from the front of the vehicle (Untouched vehicles)
	Atlas / Atlas Cross Sport	24-25	All	All	CV Boot Leaking	Customer states there is a leak from the front of the vehicle (Untouched vehicles)