

We've identified your R1T/R1S as needing a service appointment to inspect and potentially adjust the torque for fasteners on your vehicle's wheel hubs. Failing to inspect this could result in a tow.

Contact our Service Operations Center now at 1-855-RIVIAN-5 / 1-855-748-4265 to schedule an expedited appointment. Act fast to avoid issues!