



Service Bulletin

Bulletin No.: 25-NA-043

Date: February, 2025

INFORMATION

Subject: K313 Interior Object Detection Module Information When Setting DTCs

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2025	2025				

Involved Region or Country	North America
Additional Options (RPOs)	Equipped with RPO RSM

Information

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Note: Information applicable only to vehicles built with RSM. If vehicle does not have RSM, please disregard this bulletin.

K313 Interior Object Detection Module is currently only a pass-through module for the 2025 Buick Enclave with RSM RPO. Most of the time, this module will not set any MIL/CEL. This module does not support any vehicle features and will not be turned on in the future.

Ignore DTCS setting in or against this module if it is not affecting operation of the vehicle and it is not setting MIL/CEL.

If the module is causing a MIL/CEL, please follow normal service procedures found in service information for the K313 Interior Object Detection Module.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2880087	K313 Interior Object Detection Module Information	0.2 hr

*This is a unique Labor Operation for Bulletin use only.

Version	1
Modified	Released February 24, 2025

