

GPOP - Issue Review System

Part Number: 68522710A\$

Part Description: TUBE Fuel Supply

Issue Description: When there is fuel leakage at the Quick Connect of the Fuel Supply Line to the Fuel Pump Module, disconnect the Line and visually inspect the Fuel Supply Line at the Seal O-Ring area for any damaged Seal or contamination and mating connection or Line leakage. If the Fuel Supply Line is found to be the source of the leakage, only replace the Fuel Supply Line.