

<b>Reference</b>	SSM76262
<b>Models</b>	New Range Rover / L460
<b>Title</b>	24-25MY Range Rover - Third Row Seat Access Second Row Tilt Feature Inoperative
<b>Category</b>	Body
<b>Last modified</b>	07-Feb-2025 00:00:00
<b>Symptom</b>	101000 Seating
<b>Attachments</b>	1112nd Row Seat Bunny Hop Inop.pdf (1112nd Row Seat Bunny Hop Inop.pdf)

**Content**

Issue: The second-row seat 'Bunny Hop' feature for third row seat access is inoperative. When the button is depressed for third row access, the second-row seat slides forward but does not tilt forward.

Cause: The second-row seat latch motor is not overcoming initial friction to release the latch locking block.

Action: The procedures and videos available via the attached pdf and links shown below provide an interim repair guidance, while engineering investigate the concern. If a concern still exists after following this interim process, please submit a Technical Assistance case for further support.

Copy and paste these links into a browser.

Latch Lubrication  
<https://vimeo.com/1053932478/e166737678>

Latch Release  
<https://vimeo.com/1053932507/d0c3fd8b80>

Return Process  
<https://vimeo.com/1053932515/de3000522c>

anBhdhRlcnM7MjAyNS0wM0wN1QxOToxMzoxOS42MjBhOzE2NS4yMjUuMjU0Ow==