

Reference	SSM76267
Models	New Range Rover / L460
Title	Range Rover - 2nd Row Seat Unlatched Warning Displayed on vehicles with 3rd Row Seating
Category	Body
Last modified	07-Feb-2025 00:00:00
Symptom	110000 Sealing

Content

Issue: A warning message may appear on the instrument pack message center " Do not use rear (left or right) seats until latched.

Cause: This may be caused by the 2nd row seat not being fully returned after operating the 3rd row seat access "bunny hop" feature. The button to slide and tilt the 2nd row seat for access will operate as a 'one touch' operation. **However, the return buttons for the 2nd row seat must be held down until the 2nd row seat has fully returned.**

Action: **Depress and hold the 2nd row seat return button until the seat has fully returned.** If the seat fails to latch, inspect that the seat latch claw is in the open position. If further support is required, please submit a Technical Assistance case.

anBhdHRlcnM7MjAyNS0wM0wN1QxOToxNDozNC4yODNaOzE2NS4yMjUuMjU0Ow==