



**Bulletin No.:** PIT6351

**Published date:** 03/10/2025

## Preliminary Information

### PIT6351 Service A/C System Message P0071

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2024 - 2025	All	All	All	All
Cadillac	OPTIQ	2025	All	All	All	All
Chevrolet	Blazer EV	2024 - 2025	All	All	All	All
Chevrolet	Equinox EV	2024 - 2025	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional Options (RPO)</b>	
<b>Condition</b>	<b>Service AC system message. P0071 is set.</b>
<b>Cause</b>	<b>Engineering is investigating.</b>

#### Correction:

Scan vehicle for codes.

If P0071 is found follow circuit system testing in SI to test circuits.

If no circuit faults are found do not replace any parts.

Clear codes and advise customer that engineering is currently working on a design improvement.

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>Created on- 3/10/25</b>

 GM Global Brands

© 2025 General Motors. All Rights Reserved.