



WARRANTY BULLETIN

JANUARY 22, 2025

BULLETIN 2022-23 | REVISION A

CAMPAIGN N°2022-0024

⚠ CAUTION

All involved customers must be notified, all involved units must be corrected as per instruction herein.

D.E.S.S. System Activation in BUDS2

MODEL YEAR	MODEL	ENGINE
MY22	Ryker	600 ACE / 900 ACE

IMPORTANT

When receiving a vehicle for service:

- Always lookup the vehicle identification number (VIN) on the Knowledge Center to ensure all required recalls are performed.
- Always connect the vehicle to the BRP diagnostic software (BUDS) to ensure all required updates are performed.

PROBLEM


The D.E.S.S. system was not activated from the factory on certain MY22 Ryker vehicles.

SOLUTION

Activate the D.E.S.S. system in BUDS2 and program the keys.

CORRECTIVE ACTION

1. Always make sure to have the latest BUDS2 version installed.
2. Install the RF D.E.S.S. key on the RF D.E.S.S. post.
3. Connect the vehicle to BUDS2.
4. Select the "keys" tab.
5. Ensure the "Anti-Theft System" is activated.



WARRANTY

Submit a warranty claim using the following information.

For claiming procedure, refer to the online *Dealer/Distributor Warranty Guide*.

CLAIM DETAILS

Claim Type	Unit Campaign
Serial Number	Enter Serial Number
Warranty Campaign	Select <i>RYKER DESS ACTIVATION / BULLETIN 2022-23 - REPAIR-3WV-2022-0024_V1_ALL</i> from the drop-down list
Date of Repair	Repair date
Total Labor Time Paid	0.3 hour
Expiration Date	January 31, 2027