

Bulletin #: C32-0325-0614		<input type="checkbox"/> Take Note <input checked="" type="checkbox"/> Take Action	
<input type="checkbox"/> Retail Operator <input type="checkbox"/> General Manager	<input type="checkbox"/> Sales Pre-Owned <input type="checkbox"/> Sales New Car	<input type="checkbox"/> Business Manager <input type="checkbox"/> Service	<input checked="" type="checkbox"/> Parts & Accessories <input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: March 05, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC733 WINDSHIELD CLEANING CONTAINER RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

61 66 7 483 866

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing incorrect part number inside package.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC733 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC733 is valid from March 05, 2025, through March 19, 2025. The deadline for filing a claim under TEC733 is March 19, 2025. All parts must be returned to your facing RDC no later than April 02, 2025.

Please reorder the same part number if needed.

