



STAR ONLINE PUBLICATION



Case Number: S2408000020 Rev. A

Release Date: March 2024

Symptom/Vehicle Issue: Auto High Beams Come on During the Day When the Auto High Beam Control Feature is Selected on

Customer Complaint/Technician Observation: The owner complains that the **auto** high beams turn on in daylight, no auto-off control, always on. The technician has observed that the Instrument Panel Cluster (IPC) does not illuminate the auto high beam indicator, showing the system is on when the owner has selected to have the Auto controlled High Beam headlamps on.

Repair Procedure: Review the vehicle features by sales codes, vehicles require a Forward-Facing Camera Module to operate with sales code **LMS – Auto High Beam Control**. If the vehicle options list on the window sticker does not list auto high beams, the vehicle is not equipped with the option functionality.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found