

VIN:



**TIFFIN**

MOTORHOMES

---

105 2<sup>nd</sup> Street NW  
Red Bay, Alabama 35582

**NHTSA Recall # 25E-004  
Freightliner Campaign # F1016  
Cummins Campaign # C7111  
FCCC Chassis with Cummins L9 Engine Low Pressure Fuel Hose**

March 12, 2025

Dear Tiffin Motorhome Customer,

**Please see the enclosed letter** from Cummins Inc, about a safety recall Cummins has released that is applicable for the VIN listed above. For any questions regarding this safety recall, please contact Cummins Care at 1-800-CUMMINS (1-800286-6467) or visit their website at [care.cummins.com](http://care.cummins.com)

If you do not have the engine serial number or in-service date for your motorhome, please contact Freightliner Customer Service at 1-800-385-4357.

Thank you for your attention to this matter,

Tiffin Motorhomes Recall Department



## NHTSA Recall No. 25E-004 Cummins Campaign #C7111

### IMPORTANT SAFETY RECALL

This notice applies to your Cummins L9 powered equipment  
as shown on the enclosed product list.

March 11, 2025

Dear Cummins Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain Cummins L9 engines that were manufactured between August 4th, 2023 and December 21st, 2023.

#### WHY IS A RECALL BEING CONDUCTED?

Due to a manufacturing error on the low-pressure fuel hose end crimp fitting, the remote fuel filter hoses installed on the subject engines can become separated from the fuel fitting resulting in fuel leaks and lack of fuel supply to the engine. A fuel hose that becomes disconnected will result in an engine stall, increasing the risk of a crash. A fuel leak in the presence of an ignition source may increase the risk of a fire.

#### WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign C7111 L9 Remote Mount Stage 2 Fuel Hose Safety Campaign to correct this condition by replacing the two subject fuel hoses with hoses having improved connector crimps. Repair parts are currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 1 hour to complete.

#### WHAT SHOULD YOU DO?

Until the campaign is completed, Cummins advises you to periodically check the remote fuel filter hoses for signs of leaking, and immediately seek repairs if leaks are identified.

Contact the nearest Cummins Distributor or authorized warranty dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair.

***Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.***

If you have incurred expense to remedy this issue prior to the date of this notice, you may be eligible for reimbursement. Please contact your local Cummins Distributor or authorized warranty dealer.

To find a service provider near you, please use the Service Locator tool found at the Cummins sponsored website <https://quickserve.cummins.com>.



## NHTSA Recall No. 25E-004 Cummins Campaign #C7111

### WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467) or visit our website at <https://care.cummins.com>.

If you have a complaint relative to this recall, you may report it to the following:

Administrator  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue, SE  
Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

In order to serve you better, it is important to register your product. If you have not already registered your Cummins product, or if your details need to be updated, use one of the following options to register your product. Using your phone or tablet, scan the QR Code below and complete the registration online. Or, using your laptop, you can register your product at <https://prodreg.cummins.com>.

If you are no longer the owner of the engine or vehicle listed in the table, please forward this notice to the new owner or provide the new owner's contact information via email to Cummins at [cummins.campaign.administration@cummins.com](mailto:cummins.campaign.administration@cummins.com) so that we can update the contact information and notify them of this recall.

Finally, if the engine has been scrapped, or otherwise taken out of service, and replaced with another Cummins product, please contact your local Cummins Distributor or authorized warranty dealer for assistance in handling the necessary updates for your Cummins product.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator  
Cummins Inc.

Scan the QR code and complete the registration of your Cummins product online.

