

Bulletin #: C32-0325-0625		<input type="checkbox"/> Take Note <input checked="" type="checkbox"/> Take Action	
<input type="checkbox"/> Retail Operator <input type="checkbox"/> General Manager	<input type="checkbox"/> Sales Pre-Owned <input type="checkbox"/> Sales New Car	<input type="checkbox"/> Business Manager <input type="checkbox"/> Service	<input checked="" type="checkbox"/> Parts & Accessories <input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: March 25, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC749 BEARING SHELL RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

11 21 9 469 682

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing the incorrect part inside package. Parts labeled with part number 9469681 on the outside and "2" on the inside are ok for use. Please see images below.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC749 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC749 is valid from March 25, 2025, through April 08, 2025. The deadline for filing a claim under TEC749 is April 08, 2025. All parts must be returned to your facing RDC no later than April 22, 2025.

Please reorder the same part number as needed.

