

# PARTS CIRCULAR

Attention: Parts Manager  
Inventory

March 11, 2025

## Special Notice SM 19-2025:

### 1EB-422-062-B (Steering)

In order to promptly receive your credit and to improve the level of parts that reach your customers:  
Please return your inventory of the above-listed material numbers to your facing PDC, no later than 4/1/2025.

**Only parts with the listed serial numbers are affected. Example of NOT OK part:**



AFFECTED SERIAL NUMBERS		
*207 U9W178N4931*	*207 U9W178N508+*	*207 U9W178N518%*
*207 U9W178N4885*	*207 U9W178N504.*	*207 U9W178N5291*
*207 U9W178N4896*	*207 U9W178N507/*	*207 U9W178N530-*
*207 U9W178N491%*	*207 U9W178N511Z*	*207 U9W178N516/*
*207 U9W178N4942*	*207 U9W178N5190*	*207 U9W178N4863*
*207 U9W178N481+*	*207 U9W178N506\$*	*207 U9W178N527%*
*207 U9W178N4920*	*207 U9W178N513.*	*207 U9W178N522.*
*207 U9W178N4964*	*207 U9W178N523 *	*207 U9W178N521-*
*207 U9W178N4953*	*207 U9W178N517+*	*207 U9W178N4852*
*207 U9W178N4975*	*207 U9W178N526+*	*207 U9W178N514 *
*207 U9W178N4986*	*207 U9W178N5280	*207 U9W178N525/*
*207 U9W178N4997*	*207 U9W178N500X*	*207 U9W178N520Z*
*207 U9W178N501Y*	*207 U9W178N515\$*	*207 U9W178N510Y*
*207 U9W178N509%*	*207 U9W178N502Z*	*207 U9W178N524\$*
*207 U9W178N505 *	*207 U9W178N503-*	*207 U9W178N512-*

Your cooperation in using the following claims procedures is appreciated:

1. File a separate "Claim with Return" selecting "Dir Sup. Req. Return" under item type, completing your dealer comments with the Special Notice Number and Parts Circular number referenced above
2. Review Parts On Command the following day for the Delivery List document; contact your facing PDC with any problems or delays
3. Enter your 40000XXXXX delivery document number on a YELLOW DEPOT REQUEST RETURN label
4. Adhere the YELLOW DEPOT REQUEST RETURN label to the package(s) containing the returned parts
5. Include one copy of the Delivery Document with the returned part(s).

Items returned after the above-mentioned date WILL NOT be accepted on any type of return/buyback.

Please re-order required new materials using the **same part number**.