



Bulletin No.: PIP6053
Published date: 04/1/2025

Preliminary Information

PIP6053 Rear Main Seal Fold Over

Models


Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
			from to		
Chevrolet Malibu	2025		All	All 1.5 (LFV)	All



Involved Region or Country	North America
Condition	Some customers may complain of an oil leak that is coming from rear of engine
Cause	Rear main seal is folded over

Correction:

Verify leak is coming from rear main seal area, see photos below of folded seal.

If folded condition exists, repair per SI instructions.







Parts Information

Description	Part Number	Quantity
Rear main seal	Use VIN and EPC	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4066650	Crankshaft Rear Oil Seal Replacement	Use Published Time

Version History

Version	1
Modified	03/31/2025 - Created on.