

**** TECHNICAL INFORMATION NOTICE ****

DATE: March 19, 2025
TO: Mitsubishi Motors Dealer Parts & Service Managers
RE: 2025 Outlander Port Repairs
TIN NO.: TIN-25-54-003

.....


AFFECTED VEHICLES: 2025 Outlander

PURPOSE:

MMNA is in process of addressing issues on 2025 Outlander vehicles at the ports prior to them being delivered to dealerships. Stickers will be placed slightly below the headrest on the LH Driver's plastic seat cover if the issues have been addressed.

If your dealership receives a 2025 Outlander and the Discharged Battery repair (TSB-25-54-004) **has been completed, there will be a GREEN sticker on the seat cover.**

If your dealership receives a 2025 Outlander and the Abnormal Noise from Dynamic Sound Yamaha Ultimate 12 Speakers (TSB-25-54-003) repair **has been completed, there will be a BLUE sticker on the seat cover.**



If the plastic seat cover does not have a sticker on it, please check the VIN to see if the Technical Service Bulletins are applicable and, if so, complete the repairs immediately.

Again, note that it is CRITICAL that these repairs are completed IMMEDIATELY, and prior to the vehicles being sold and delivered to customers.

Thank you for your help in our quest to provide vehicles of the highest quality.