



Bulletin No.: PIP6057
Published date: 04/11/2025

Preliminary Information

PIP6057 Rear Differential Moan Noise in AWD

Models

Brand: Model: Model Years:		VIN: from to		Engine:	Transmissions:
Chevrolet Equinox		2025 - 2026	All	All All	All
GMC Terrain		2025 - 2026	All	All All	All
Involved Region or Country:	North America				
Condition:	The vehicle may present with a concern of a moaning type of noise in the rear of the vehicle while in AWD.				
Cause:	The rear differential may be the cause of the noise.				

Correction:

If the moan noise is confirmed to be coming from the rear differential, do not replace the rear differential.

Engineering is currently investigating

In the meantime please advise customer they may continue to drive the vehicle

The PI will be updated or replaced with TSB once a determination has been made

If the rear differential is not the cause of the moaning type of noise, continue using SI diagnostics.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description:	Labor Time:
* 3086068	Diagnosis of rear differential moan noise and return to customer	0.3 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	04/11/2025 - Created on.