



SIB 34 01 25

"SERVICE SOLUTION: Front Calipers Leaking" After sitting idle for long periods


2025-04-22

MODEL

Model	Model Description
KA1	R 1300 GS
KA2	R 1300 GS Adventure

SITUATION

One or both of the front brake caliper/s are leaking after sitting idle for long periods of time. They only leak at low internal pressures.



PROCEDURE

**DO NOT REPLACE** the calipers.

The repair is to replace the Brake piston with seals set. Existing fluid residue on the caliper must be cleaned with a suitable cleaner. Check ETK for the correct part number.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture\\_as\\_pdf 34 01 25 SESO Front Calipers Leaking.pdf](#)

