



Bulletin No.: PIT6286A
Published date: 04/16/2025


Preliminary Information

PIT6286A Passengers Side Outside Mirror Reflection

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado EV Models	2024 - 2025	All All	All	All
GMC	Sierra Denali EV	2024 - 2025	All All	All	All
Cadillac	Escalade IQ	2025	All All	All	All
GMC	HUMMER EV	2022 - 2025	All All	All	All
GMC	HUMMER EV SUV	2024 - 2025	All All	All	All

Involved Region or Country	North America
Additional RPO(s)	Check VIS for any vehicle over 10,000 # GVW
Condition	A customer/driver could notice that the reflection/view of the passenger side outside mirror is different than the reflection/view of the drivers side outside mirror.
Cause	MVSS 111 requires that the passenger side mirror glass be flat (not convex) when the vehicle exceeds 10,000 # GVW.



Correction:


This is a normal characteristic of the vehicle and no repairs should be attempted.

Dealer technicians should educate the customer on the FMVSS requirement.

Any passenger side mirror replacements due to this customer concern will be charged back to the dealer.

Version History

Version	2
	11/25/2024 - Created on 4/16/2025- Updated Models

 GM Global Brands

© 2025 General Motors. All Rights Reserved.