


Subject: Information on L3B/L2R Timing Chain Tensioner Gasket

Brand:	Model:	Model Year:		Build Date:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2025			L3B, L2R	
Chevrolet	Colorado	2023	2025				
	Silverado 1500	2019	2021				
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = WY)	2022	2022				
	Silverado 1500 New (RPO J22, VIN Digit 5 = A/D)						
	Silverado 1500	2023	2025				
GMC	Canyon	2023	2025				
	Sierra 1500	2019	2021				
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8/9)	2022	2022				
	Sierra 1500 New (RPO J22, VIN Digit 5 = H)						
	Sierra 1500	2023	2025				

In- volved Re- gion or Coun- try	North America
Con- di- tion	Some technicians may comment on when removing the Timing Chain Tensioner, a Timing Chain Tensioner Gasket may not be present.

Information



5512284

This is per GM design; the Timing Chain Tensioner Gasket (3) is **no longer necessary**.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Version	1
Modified	Release March 28, 2025