

Bulletin #: C32-0425-0627		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: April 04, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC753 SCR CONTAINER RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

16 19 7 295 653

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing connection piece not centered. Parts containing the connection piece in between the two lines shown below are ok for use. Please see images below.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC753 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC753 is valid from April 04, 2025, through April 18, 2025. The deadline for filing a claim under TEC753 is April 18, 2025. All parts must be returned to your facing RDC no later than May 02, 2025.

Please reorder the same part number as needed.

